



# Technical / News Bulletin

UK

BULLETIN NO.:

UK033

DATE ISSUED

29/05/2014

## BULLETIN DETAILS

**Product Group:** Power

**Model Affected:** Quickie Salsa HD family / Jive

**Effective Date:** Immediate

**Serial No. Effective From:** N/A

**Bulletin Subject:** Recline Actuator with VR2 No-Go

### Subject of Bulletin:

This bulletin is to advise all customers of a change to No-Go status (non-compatibility) between the Powered Recline and the VR2 Control system.

After extensive testing it has been determined that the power recline actuator when used in conjunction with the current limiting circuitry within the VR2 controller, does not meet Sunrise Medical expectations for durability. The power recline actuator will, however, still function correctly within the expected lifetime of the wheelchair.

For this reason, this option will be deemed as unavailable with the VR2 control system.

The selection of the powered recline option with a VR2 control system, will become a No-Go and the R-net control system must be selected when powered recline is required on the Quickie Salsa M HD, Salsa R<sup>2</sup> HD and Quickie Jive powered wheelchairs.

### Literature Affected:

**Sunparts:** No updates required

**Order Forms:** Updated to add powered recline / VR2 controller no-go

**Website:** No change

**Owners Manual:** No change

If you have any questions regarding this bulletin, please do not hesitate to contact:

Customer Services	Customer Support	Technical Service Centre	E-mail
<b>Telephone:</b>	<b>+44 (0)845 605 66 88</b> <b>Option 2</b>	<b>+44 (0)845 605 66 88</b> <b>Option 3</b>	<a href="mailto:enquiries@sunmed.co.uk">enquiries@sunmed.co.uk</a>
<b>Fax:</b>	<b>+44 (0)845 605 66 89</b>	<b>+44 (0)845 605 66 89</b>	<a href="mailto:help.technical@sunmed.co.uk">help.technical@sunmed.co.uk</a>