



Technical / News Bulletin

UK

BULLETIN NO.:

TB UK050

DATE ISSUED

31/03/2015

BULLETIN DETAILS

Product Group:	Manual Wheelchairs		
Model Affected:	Breezy Moonlite		
Effective Date:	Immediate	Serial No. Effective From:	Implemented since February 2015
Bulletin Subject:	Improvement to backrest bracket		

Description of issue

A small number of Breezy Moonlite folding backrest brackets have been subject to clip rotation when operating the folding mechanism. Long term this can result in possible breakages of the clips.

Solution – Refer to image below

The rigidity of the backrest clip has been improved by adding more material to the clip and providing a deeper gauge for the pivot pin, thus restricting the amount of possible rotation of the clip (see picture below).



Benefit to customer

1. Improved strength and protection against clip rotation and breakages.

Literature Affected:

Sunparts:	Running change. No updates required
Order Forms:	No changes required
Website:	No changes required
Owners Manual:	No changes required

If you have any questions regarding this bulletin, please do not hesitate to contact:

Customer Services	Customer Support	Technical Service Centre	E-mail
Telephone:	+44 (0)845 605 66 88 Option 2	+44 (0)845 605 66 88 Option 3	enquiries@sunmed.co.uk
Fax:	+44 (0)845 605 66 89	+44 (0)845 605 66 89	help.technical@sunmed.co.uk