



ASSEMBLY INSTRUCTION

Seat cushion





Description	Item no.
Seat cushion comfort + Trevira SW 39	☐ 3514639
Seat cushion comfort + Trevira SW 42	☐ 3514642
Seat cushion comfort + Trevira SW 45	☐ 3514645
Seat cushion comfort + Trevira SW 48	☐ 3514648
Seat cushion comfort + Trevira SW 51	☐ 3514651
Seat cushion comfort + Trevira SW 54	☐ 3514654
Seat cushion comfort + Vinyl SW 39	☐ 3514739
Seat cushion comfort + Vinyl SW 42	☐ 3514742
Seat cushion comfort + Vinyl SW 45	☐ 3514745
Seat cushion comfort + Vinyl SW 48	☐ 3514748
Seat cushion comfort + Vinyl SW 51	☐ 3514751
Seat cushion comfort + Vinyl SW 54	☐ 3514754





1







Sunrise Medical HCM B.V.
Vossenbeemd 104
5705 CL Helmond
The Netherlands

T: +31 (0)492 593 888
customerservice@sunrisemedical.nl
www.SunriseMedical.eu