


	Technical / News Bulletin <b>UK</b>	<b>BULLETIN NO.:</b>
		<b>TB0601</b>
		<b>DATE ISSUED</b>
		10/08/2019

**BULLETIN DETAILS**

<b>Product Group:</b>	Sterling		
<b>Model Affected:</b>	S400, S425 & S700		
<b>Effective Date: See Below</b>	<b>Serial No. Effective From:</b>	N/A	
<b>Bulletin Subject:</b>	Sterling S-Series O2 tank holder discontinuation		

**Description of Issue / Solution:**

Following market surveillance with immediate effect the O2 tank holder accessory (22219093) which is available on the Sterling S-Series has been discontinued.



The order form and brochure will be updated to reflect this discontinuation.

Customer Services	Customer Support	Technical Service Centre	E-mail
<b>Telephone:;</b>	<b>+44 (0)845 605 66 88 Option 1-1</b>	<b>+44 (0)845 605 66 88 Option 1-2</b>	enquiries@sunmed.co.uk
<b>Fax:</b>	<b>+44 (0)845 605 66 89</b>	<b>+44 (0)845 605 66 89</b>	help.technical@sunmed.co.uk